

SYNTHO-GLOSS[®] XT

UTILITY FIELD INSTALLATION: STEEL REINFORCED CONCRETE



Problem

A 20 year old pre-stressed concrete pipe is leaking large amounts of hydrogen sulfide gas, liquefying to sulfuric acid, causing pipe deterioration.

Conditions

Sewage is percolating through the ruptured municipal force main which is buried 8 feet underground. Sulfuric acid has eaten through 2 feet of the pipe's crown.

Solution

The crew used an 8" by 50' roll of Syntho-Glass[®]XT to wrap 8 layers over the 2' repair section, plus an additional 4 to 5 feet on either side of the patch, as a precautionary measure.

Result

The wrapped area of the pipe is now as strong, or stronger, than the original pipe and allowed the city to save thousands of dollars, as compared to traditional repairs with couplings and forced main shutdown.

©Neptune Research Inc. (NRI). NRI[®] and Syntho-Glass[®]XT are registered trademark of NRI. Please contact your local NRI distributor or office for the most current product specifications. User shall determine suitability of product for use and assumes all risk. XT CS 0811

NRI[®]
Innovative Composite Solutions